



Adhesive Templates Canada - Technical Bulletin

July 14, 2020

Part# 84682662

Description – X31

Details – The red coloring on the OEM nameplate softened up and lost adhesion to the nameplate after it had soaked overnight in Blue Bear 280AH

Recommendation – avoid immersing nameplate in Blue Bear. Either have only a thin layer of Blue Bear in the soaking tray so that only the original adhesive comes in contact with the Blue Bear, or use traditional method to remove old adhesive such as razor blade or eraser wheel.

